



Long Sleeve Industrial Work Shirt

PRODUCT MEASUREMENTS

	S	M	L	XL	2XL	3XL	4XL	5XL	6 XL
Chest	42	46	50	54	57	60	63	66	69
Sleeve Length	34 1/4	34 3/4	35 1/4	35 3/4	36 1/4	36 3/4	37 1/4	37 3/4	38
Center-back Length	32 1/8	32 1/2	32 3/4	33	33 1/4	33 1/2	33 3/4	34	34 1/8

CHEST

Measured across the chest one inch below armhole when laid flat.

SLEEVE LENGTH

Measure From CB Neck to Shoulder Point to Finished Sleeve Hem.

SIZE CHART

	S	M	L	XL	2XL	3XL	4XL	5XL	6 XL
Neck	14-14 1/2	15-15 1/5	16-16 1/2	17-17 1/2	18-18 1/2	19-19 1/2	20-20 1/2	21-21 1/2	22-22 1/2
Sleeve	33	33 1/2	34	34 1/2	35	35	35	35	35

NECK

Measure around the base of the neck, inserting a finger or two between the tape and neck for comfort.

ARM

Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.